

PUBLIC NOTICE

Intertek Warns of Unauthorized Intertek Certification Document and Unauthorized use of ETL Certification Marks for BLOWTHERM SPA Paint Spray Booth Lighting Fixtures

Published: July 27, 2016 (Updated: December 8, 2016)

The following is a notification from Intertek that an Authorization to Mark (ATM) Certification Document and products are known to be in the market place bearing unauthorized ETL Certification Marks for the United States and Canada. The unauthorized products have not been evaluated by Intertek and it is not known if they comply with <u>any</u> safety requirements.

Product Description	Paint Spray Area Lighting Fixtures for Use in Hazardous Locations Identified Models: LF-4-120, LF-4-277, LF-4-347, LF-6-120, LF-6-277, LF-6-347, 20013-1, and Extra L4-32-120		
Manufacturer	BLOWTHERM SPA		
Number of Units	Unknown		
Identification	Unauthorized ATM: See page 2 for full details (Models LF-4-120, LF-4-277, LF-4- 347, LF-6-120, LF-6-277, LF-6-347, 20013-1) Product: Unauthorized cETLus Mark and control number 3052925 identifying certified to UL std. 844 and CAN/CSA std. C22.2 No. 137 M91 - See nameplate on Page 2 for example. (Known models LF-4-120, LF-4-277, LF-4-347, LF-6-120, LF-6- 277, LF-6-347, 20013-1, and Extra L4-32-120) Note: <u>There are no</u> BLOWTHERM SPA Paint Spray Area Lighting Fixtures for Use in Hazardous Locations Listed by Intertek. Other unauthorized model number may also exist.		
Reported Hazards	Unknown		
Sold at	Unknown		
What to do	Immediately discontinue use		



Г

Unauthorized ATM and Product Nameplate

٦

	î Ir	ttertek Testing Services NA Ltd.
	AUT	THORIZATION TO MARK
	made in accordance v	2003
	Applicant:	Blowtherm Spa. Via Guido Reni, 5, 35134 Padova, Italy (39) 049 9300229
	Manufacturer:	Blowtherm Spa.
	Contact:	Via Borgo, Padova 89, 35012 Camposanpiero (PD) Mr. Vincenzo Patron, (39) 049 9300229
	Reference Report Ne Product Covered:	
	Description:	Paint Spray Area Lighting Fixture. For use in Hazardous Location Paint Spray Area Lighting Fixture.
	Model:	For use in Hazardous location as Class 1 Division 2 Designation LF-4-120, LF-4-277, LF-4-347, LF-6-120, LF-6-277, LF-6-347, 20013-1
	Standard(s):	UL 844 11 th edition, CSA C22.2 No: 137 M81.
JN	This is ceed if e, w is $d \leftarrow i$ end d so by $fe \cdot ing \leftarrow rv_1$ and	al evis ns, c, s the rc erty of tertely es ng Serv es fe the noa e (the ne in the pr entat e of int tek is of th nsfe ble.
		C C C C C C C C C C C C C C C C C C C
	-	Intertek Testing Services NA Inc. 24 Groton Avenue Cortland, NY 13045-2014 USA
		Data
	Authorized by:	William Starr

FOR USE IN	CAL LIGHTING FIXTURE HAZARDOUS LOCATION 844, 11th EDITION)
Exercise Intertek 3052925	INDOOR APPLICATION HAS BEEN CERTIFIED FOR USE IN CANADA AND UNITED STATE OF AMERICA Conforms to/ a: - UL std. 844 Certificed to / Certificae a: CAN/CSA std.22,2 No 137 M91
CODE: 71L41EF	MODEL EXTRA L 4-32-120
SERIAL No 5L81702	YEAR 2015
ELECTIRCAL DRAWING	3: PL00004
V 120 Ph 1 Hz	60 TOT. F.L.A. 0.94
LAMP TYPE F32T8	No 4 W 128
1000	
Party Column	DWTHERMI BPA DIRED PADOVA, W COMMINECTION (PD) (TALY OUZZI Past 126 Date statistic)