

545 E Algonquin Road, Suite H Arlington Heights, IL 60005 USA

Telephone: 847-439-5667 intertek.com

Published: Revised: August 27, 2019

Public Notice ID: 19-26 Page 1 of 2

Counterfeit Intertek Certified Product Notification / Notification de produit certifié Intertek contrefaite

Red Copper 5 Minute Chief - Electric Grill Pan

Notification Type:	Counterfeiting / Contrefaçon
Certification Type:	Not Intertek Certified

Notification

Intertek notifies consumers, retailers and distributors that we have been made aware of counterfeit products in the marketplace, as identified below, bearing Intertek Certification Marks. / Intertek informe les consommateurs, les détaillants et les distributeurs que nous avons été informés des produits contrefaits sur le marché, comme indiqué ci-dessous, portant des marques de certification Intertek.

Company Identification

Telebrands Corporation, Red Copper 5 Minute Chef

Product Identification

COUNTERFEIT PRODUCT - Grill pan model 22852A1 Batch number / Barcode: 97298029127 labeled with the Intertek Certification Mark for the US and Canada (cETLus) with Control Number 5010518.

Product is red plastic, double sided electric copper ceramic infused non- stick grill pan. The product was sold online, in particular via eBAY. A recall has been initiated by EU Economic Operators as reported on Rapex. See page two of this Notification for RAPEX Link.

Hazard Involved

Insulation between the mains connection and the conductive hot plate is insufficient. Consequently the hot plate could become live, leading to the user receiving an electric shock if inadvertently touched. The product was sold online, in particular via eBAY.

A recall has been initiated by EU Economic Operators as reported on Rapex of this COUNTERFEIT PRODUCT. See page two for Link.

What To Do

Use of these products should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation de ces produits doit être immédiatement abandonnée et retourner au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.



Published: Revised:

August 27, 2019

Photos, Images and RAPEX Link

545 E Algonquin Road, Suite H Arlington Heights, IL 60005 USA

Telephone: 847-439-5667 intertek.com

Public Notice ID: 19-26 Page 2 of 2

https://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/?event=viewProduct&reference=A12/0806/19&Ing=en

